RISK ASSESSMENT: 36-42 Helmton Road



Address of Building	36-42 Helmton Road, Woodseats, S8 8QJ	Date of Assessment	16/11/2021	Name of person undertaking assessment	Rob Batley
---------------------	--	--------------------	------------	---------------------------------------	------------

Hazard and Associated	How are the risks already controlled? What extra controls are needed?			
Risks (all at risk)				
Fire	All routes through the hall, stairs and landing to be kept clear			
	The front door is to be kept unlocked while the building is in use			
	Ensure all fire extinguishers are properly tested, in date and secured correctly. This should be checked on a monthly basis.			
Hazardous Substances	All hazardous substances to be stored securely in accordance with manufacturer's instructions			
	Any hazardous substances to have a relevant COSHH form available			
Legionaries' Disease from intermittently used pipework	All taps and showers to be run for at least one minute every month			
Wear and Tear	Monthly check of the general building to be undertaken			
Slips, Trips and Falls	Steps to have yellow edging around the edge, where the steps are not a full flight of stairs			
	All common areas to be kept clear			
	Any spillages or leakages to be cleaned			
Kitchens	Any use of kitchens to be supervised by an appropriate adult			
Electrical Hazards	All electrical items brought into the premises to be PAT tested			
	All on site electrical appliances to be PAT tested within their individual risk assents. This is annually by default.			
Garage	Access not granted to the garage unless authorised.			
	Adults in the group should ensure this area remains out of bounds.			
COVID-19	48 hours to be left between groups using the building where possible			
	Should 48 hours not be possible, a deep clean of major touch points of the building to be undertaken			
	Building to have a regular deep clean			
	Anti-bacterial gel to be available at the entrance/exit and throughout the building where it is deemed appropriate			

Actions for Building Owners:

- Ensure hand gel dispensers are distributed around the building, topped up, instructions are provided how to top up, and where to find extra gel.
- Ensure on-brand signs/posters are displayed where relevant around the building